



Quick User Guide

1/2" Corrugated Coax – Termination Instructions

Note to Field Technician: It is extremely important that you follow these steps closely for a perfect termination. Spending the few extra seconds to ensure this is done correctly will save you lots of time, money and frustration in trying to find a compromised termination during the commissioning and optimization process of the DAS.

It is **MANDATORY** that frequency return loss testing be completed on ALL cables made in the field and the test results documented. A benchmark of no less than 20dB must be achieved across all frequency bands.

215 Celebration Place
Kissimmee FL 34747
Suite 190

DUNS Number: 005013494
NCAGE Code: 561L1

Dennison Jurawan ~ Technical Sales Manager
Email: sales@jdteck.com
Tel: 321-939-3816
Fax: 321-939-3819




A+ Rating






Tools required for this process. Approximate time to complete termination: **2 mins.**



Use cable cutter to cut cable to appropriate length.



Apply pressure to cutter, but not too much.




As you continue to squeeze, move hand back & forth.



Try to move as much as 90 degrees for a clean circular cut.




If coax is bent, please straighten.




Do not attempt to strip coax while bent.




Use tool to prep cable.




Use drill at **HIGH SPEED** (Not slowly). Apply pressure.




You should see excess material exiting tool as you drill.








Run for about **2-3 secs** then **STOP** to check results.




Your cut **MUST** be center-line of a peak.




Center-line of a peak will ensure a perfect termination.






Use flaring tool on cable after connector is in place.



A good flare will have both sleeve and shield aligned.




Use brush to clean off shavings. **DO NOT BLOW** on it.




Align connector halves together.




Tighten connector with hand till snug.



Use wrenches to tighten properly.




Examine connector to make sure it's a solid connection.



Slide up heat shrink supplied with connector.



Apply heat from heat gun.



Use test equipment to verify return loss benchmark. **>20dB**